

**NONCOMPLIANCE 24-HOUR NOTIFICATION FAX REPORT**

State Form 52416 (10-05)
Indiana Department of Environmental Management
Office of Water Quality

2ND FAX -

Confirmation of leak stopped

INSTRUCTIONS: Complete all parts of this form and fax it to Office of Water Quality, Compliance Evaluation Section at (317) 232-8637 or 232-8406. Thorough completion of this report will satisfy the Office of Water Quality (OWQ) telephone and 5-day written noncompliance notification reporting requirements of your NPDES permit. To speak with someone in OWQ, call (317) 232-8670.

Any noncompliance which may pose a significant danger to human health or the environment must be immediately reported to the Emergency Response Section spill response line at: (317) 233-7745 or toll free within Indiana at (888) 233-7745.

FACILITY INFORMATION				
Facility Name:		County:		NPDES Permit Number:
BP Products NA, Inc. Whiting Business Unit		Lake		IN 0000108
Individual Reporting:		Phone Number:		Reporting Date:
Tim Chen		219-473-1286		01/25/2013 (initial) 02/14/2013 (follow up)
NONCOMPLIANCE INFORMATION				
Date:	Outfall:	Parameter:	Permit Limit: (Units/Daily/Weekly/Ave/Max/Min)	Monitored Value:
01/23/12	002	Benzene, Toluene, Ethylbenzene	100 ug/L (notification level) per condition II.C.9.a	Benzene 1300 ug/L, Toluene 1100 ug/L, Ethylbenzene 110 ug/L
Date:	Outfall:	Parameter:	Permit Limit: (Units/Daily/Weekly/Ave/Max/Min)	Monitored Value:
1/24/13	002	Benzene, Toluene, Ethylbenzene	confirmation of leak stopped	Benzene 6.9 ug/L, Toluene 34 ug/L, Ethylbenzene 5.6 ug/L
Description of the Noncompliance and its Cause: The cause of this incident is due to a heat exchanger (E1) leak at production unit 11A Pipestill that released petroleum intermediate Light Naphtha into the once through cooling water system. A water sampling at 11:15 AM on January 23, 2013 at the #6 Separator effluent indicated the presence of benzene, ethylbenzene and toluene in concentrations above the notification level. #6 Separator discharges to Outfall 002. The analytical results were received on January 25, 2012.				
Description of the Period of Noncompliance, Including Exact Dates and Time, and if the Noncompliance has not been Corrected, the Anticipated Time it is Expected to Continue: Incident period lasted less than 3 hours approximately from 1/23/13 0900 to 1/23/13 1145. The personnel at Leakfront WWTP observed no odor, and no visible oil sheen in #6 Separator during the incident.				

Document ID WBU-DENV-2G05-45311

Steps Taken or Planned to Reduce, Eliminate, and Prevent Reoccurrence of the Noncompliance:

The refinery have engaged in the following corrective measures to stop or minimize the leaks.

1. E1 heat exchanger was blocked in to contain the leak. It is placed out of service for repair.

New
Follow Up Note-

A subsequent water sample was taken at #6 Separator effluent on 1/24/2013. The analytical results indicate that the leak has been stopped.

CERTIFICATION AND SIGNATURE

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

SIGNATURE: *Jim Chen*

DATE: 2-18-13

 *** FAX TX REPORT ***

TRANSMISSION OK

JOB NO. 1944
 DESTINATION ADDRESS 813172328637
 SUBADDRESS
 DESTINATION ID IDEM 24-hr Notification
 ST. TIME 02/19 12:49
 TX/RX TIME 00' 25
 PGS. 2
 RESULT OK



NONCOMPLIANCE 24-HOUR NOTIFICATION FAX REPORT

State Form 52416 (10-05)
 Indiana Department of Environmental Management
 Office of Water Quality

2ND FAX -
 Confirmation of leak stopped

INSTRUCTIONS: Complete all parts of this form and fax it to Office of Water Quality, Compliance Evaluation Section at (317) 232-8637 or 232-8406. Thorough completion of this report will satisfy the Office of Water Quality (OWQ) telephone and 5-day written noncompliance notification reporting requirements of your NPDES permit. To speak with someone in OWQ, call (317) 232-8670.

Any noncompliance which may pose a significant danger to human health or the environment must be immediately reported to the Emergency Response Section spill response line at: (317) 233-7745 or toll free within Indiana at (888) 233-7745.

FACILITY INFORMATION				
Facility Name:		County:	NPDES Permit Number:	
BP Products NA, Inc. Whiting Business Unit		Lake	IN 0000108	
Individual Reporting:		Phone Number:	Reporting Date:	
Tim Chen		219-473-1286	01/25/2013 (initial) 02/14/2013 (follow up)	
NONCOMPLIANCE INFORMATION				
Date:	Outfall:	Parameter:	Permit Limit: (Units/Daily/Weekly/Ave/Max/Min)	Monitored Value:
01/23/12	002	Benzene, Toluene, Ethylbenzene	100 ug/L (notification level) per condition II.C.9.a	Benzene 1300 ug/L, Toluene 1100 ug/L, Ethylbenzene 110 ug/L
Date:	Outfall:	Parameter:	Permit Limit: (Units/Daily/Weekly/Ave/Max/Min)	Monitored Value:
1/24/13	002	Benzene, Toluene, Ethylbenzene	confirmation of leak stopped	Benzene 6.9 ug/L, Toluene 34 ug/L, Ethylbenzene 5.6 ug/L
Description of the Noncompliance and its Cause: The cause of this incident is due to a heat exchanger (E1) leak at production unit 11A Pipestill that released petroleum intermediate Light Naphtha into the once through cooling water system. A water sampling at 11:15 AM on January 23, 2013 at the #6 Separator effluent indicated the presence of benzene, ethylbenzene and toluene in concentrations above the notification level. #6 Separator discharges to Outfall 002. The analytical results were received on January 25, 2012.				
Description of the Period of Noncompliance, including Exact Dates and Time, and if the Noncompliance has not been Corrected, the Anticipated Time it is Expected to Continue: Incident period lasted less than 3 hours approximately from 1/23/13 0900 to 1/23/13 1145. The personnel at Leakfront WWTP observed no odor, and no visible oil sheen in #6 Separator during the incident.				